

Archaeological Resources

Airport Vicinity Development Checklist

Parking Study

Trip Generation Comparison

Parking Master Plan



## ADOBE FIRE PROTECTION, LLC

	1	FLOW TEST	SUMMARY		RUC #305001
Project Address: _ [	_ ^		Whote	Dove	
Permit Number:	2-61384	MANANCE - 11 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	9		
Date of Test: 3	112/20		Time	e of Test: 8	:15 AM
	•	ction map iden	•	ssure and (#2)	flow hydrant used
	ocation of pressun hydrants and n	-	-	vith cross stree	ts and distance
·	Charter on st wethers f	atic s			
	wethers f	ied a 7			
		Cact	tus		
TEST DATA		10%			
Static Pressure:		// psi	Hydrant O	rifice Diamete	r: 2,5
Residual Pressure	: 89	psi	Coefficient	of Discharge:	whomistoodikohammakkaanaanaana
Pitot Reading:	65	psi			
Flow GPM:	1350x	gpm	/)		
Conducted By:	Zack	HORAMEK	34		
Witnessed By:	12 to st. "	cothack	# <sup>4</sup> *		

723 E. University Dr., Mesa, AZ 85203 Office: (480) 539-8868 Fax: (480) 539-8437